

08-01-'06 14:48 FROM-MKC&H LLP

9497527049

T-508 P004/009 F-516

App. Ser. No. 10/608,008

Docket No. AB-1581-1C US

Amendment dated Aug. 1, 2006

Ref. No. LW5007US (CPA)(CA)

Reply to Office action of May 3, 2006

Amendments to the Specification:

Please replace paragraph [0079] with the following amended paragraph:

[0079] Insertion holes 640 for the protrusions 262a, 264a of the inverter supporting bars 262, 264 shown in FIG. 3 are formed at the corresponding portions of an inverter 600. Preferably, guide grooves 645 are formed at the portions corresponding to the inverter supporting bars 262, 264 so that the inverter supporting bars 262, 264 can be more firmly fixed. In addition, a coupling hole 650 is formed at the portion corresponding to the boss 136 [[260]] on the rear case 100 as shown in FIGS. [[FIG.]] 2 and 13, so as to be coupled to the boss 136 [[260]] by a screw.